











DIMENSIONS

SYMBOL	INCHES			Millimeter		
	MIN.	NOM.	MAX.	MIN.	NOM.	MAX.
A	0.000	---	0.045	0.900	---	1.150
A1	0.000	---	0.004	0.100	---	0.100
a	0.035	0.038	0.041	0.900	0.975	1.050
b	0.012	0.016	0.020	0.300	0.400	0.500
c	0.004	---	0.008	0.100	---	0.200
D	0.110	0.114	0.118	2.800	2.900	3.000
e	0.047	0.050	0.055	1.200	1.275	1.400

